



## NOTICES OF CORRECTIVE ACTION INDEX

PLEASE FIND LISTED BELOW ALL NOTIFICATIONS, SAFETY ALERTS AND SERVICE BULLETINS RELEVANT FOR THE SEAMAX M-22 QUALIFIED TO THE LSA REQUIREMENTS

AIR\_NCAI\_001 Revision n°01

Initial Issue Date: Feb 19th, 2008

Updated: July 01rd, 2017

Document Type	Document Code	Subject	Revision	Issue Date	Model	S/N of Affected Aircraft	Compliance	Status
<b>1. SAFETY ALERTS</b>								
<b>2. SERVICE BULLETINS</b>	SB-001-08	Nicopress inspection	0	12/03/2008	Seamax M-22	038 to 055	<b>MANDATORY</b>	<b>RELEASED</b>
	SB-001-09	Wingstrut bolt	0	02/03/2009	Seamax M-22	01 to 025	<b>MANDATORY</b>	<b>RELEASED</b>
<b>3. NOTIFICATIONS</b>	NT-001-17	Notification LSA BRA and USA	0	01/08/2017	Seamax M-22	All	<b>INFORMATION</b>	<b>RELEASED</b>
<b>4. TECHNICAL INFORMATION</b>	TI-001-08	Engine thrust line	0	22/06/2008	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-002-08	New vortex generator size and	0	22/06/2008	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-003-09	Instructions for fins installation	0	03/02/2009	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-003-11	Bilgde pumps and water inside hull	0	05/03/2011	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-004-09	travel adjustments on stabilator	0	02/01/2010	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-005-15	Instalation of plug in wing tips	0	02/03/2015	Seamax M-22	All	<b>RECOMMENDED</b>	<b>RELEASED</b>
	TI-006-17	Folding wing instructions	0	18/05/2017	Seamax M-22	All aircraft folding wing	<b>RECOMMENDED</b>	<b>RELEASED</b>

### AIRMAX CONSTRUÇÕES AERONÁUTICAS LTDA

Rod. SP-344, SJBV/Aguai Km219 – Aeródromo de São João da Boa Vista - Hangar 01 - SDBV

São João da Boa Vista - São Paulo - Brasil - CEP 13.870-970

Website: [www.seamaxaircraft.com](http://www.seamaxaircraft.com) - E-mail: [support@seamaxaircraft.com](mailto:support@seamaxaircraft.com)