

	<h2 style="text-align: center;">NOTICES OF CORRECTIVE ACTION INDEX</h2> <p style="text-align: center;">PLEASE FIND LISTED BELOW ALL NOTIFICATIONS, SAFETY ALERTS AND SERVICE BULLETINS RELEVANT FOR THE SEAMAX M-22 QUALIFIED TO THE LSA REQUIREMENTS</p>						AIR_NCAI_001 Revision nº00 Initial Issue Date: Feb 19th, 2008 Updated: August 01, 2017	
Document Type	Document Code	Subject	Revision	Issue Date	Model	S/N of Affected Aircraft	Compliance	Status
1. SAFETY ALERTS								
2. SERVICE BULLETINS	SB-001-08	Nicopress inspection	0	03/12/08	Seamax M-22	038 to 055	MANDATORY	RELEASED
	SB-001-09	Wingstrut bolt	0	03/02/09	Seamax M-22	01 to 025	MANDATORY	RELEASED
3. NOTIFICATIONS	NT-001-17	Notification LSA BRA and USA	0	08/01/17	Seamax M-22	All	INFORMATION	RELEASED
4. TECHNICAL INFORMATION	TI-001-08	Engine thrust line	0	06/22/2008	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-002-08	New vortex generator size and position	0	06/23/2008	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-003-09	Instructions for fins installation	0	02/03/09	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-003-11	Bilgde pumps and water inside hull	0	03/05/11	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-004-09	travel adjustments on stabilator	0	01/10/10	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-005-15	Instalation of plug in wing tips	0	03/02/15	Seamax M-22	All	RECOMMENDED	RELEASED
	TI-006-17	Folding wing instructions	0	05/18/2017	Seamax M-22	All aircraft folding wing	RECOMMENDED	RELEASED